




Replacement Sheets

1/3



The diagram illustrates a packet scheduling process. It shows a sequence of packets numbered 20 to 34. The sequence is divided into three phases: 'Assessment phase' (packets 20-23), 'Assignment phase' (packets 24-29), and 'Acknowledged group' (packets 30-34). Arrows indicate the flow of packets between these phases. A 'delay' is indicated between packets 35 and 36. The diagram also shows a 'Signal' and 'Assigned' signal.

Packet Number	Phase
20	Assessment phase
21	Assessment phase
22	Assessment phase
23	Assessment phase
24	Assignment phase
25	Assignment phase
26	Assignment phase
27	Assignment phase
28	Assignment phase
29	Assignment phase
30	Acknowledged group
31	Acknowledged group
32	Acknowledged group
33	Acknowledged group
34	Acknowledged group

FIG. 2




FIG. 3